



A*1



B*1



C*2



D*1



E*4




F*4




G*4



H*1




Step 1: A and B are inserted into C and aligned with the screw holes.




Step 2: Tighten the screw E.




Finished.


				 M6*65	 M6*20			
A*1	B*1	C*2	D*1	E*4	F*2	G*6	H*6	I*1




Step 1:A and B are inserted into C and aligned with the screw holes.



Step 2:Tighten the screw E.



Step 3:Tighten the screw F.



Finished.