



A*1



B*1



C*2



D*1



M6*65

E*4




F*4




G*4



H*1



Step 1: A and B are inserted into C and aligned with the screw holes.



Step 2: Tighten the screw E.



Finished.



A*1



B*1



C*2



D*1



M6*65



M6*20




G*6




H*6




I*1




Step 1: A and B are inserted into C and aligned with the screw holes.



Step 2: Tighten the screw E.



Step 3: Tighten the screw F.



Finished.