

Risk analysis / Technical documentation according to EU 2023/988 §9 (2)* for products not subject to other Union harmonisation legislation within the meaning of Section 3 (27)**							
	General informa	tion	Article	photo			
Date of first version		11-12-2024	(without packaging, complete set				
If revisions to the risk analysis have been made	de date of revision		items to	r groups)			
ii revisions to the risk analysis have been mad							
	General article infor						
Article name or article group name	timber panel beech/ timmerp						
relevant HORNBACH article numbers****		314 (See for complete list of article numbers Part V letter of correspondan)					
relevant supplier article numbers relevant GTINs		complete list of article numbers Part V letter of correspondan) e for complete list of Gtins Part V letter of correspondan)					
Brands	Buildify						
	General supplier info						
Name and address of the supplier	e and address of the supplier Deli-Home Netherlands B.V., Stadhuisplein 70, 4203 NS, Gorinchem						
A solid lumber panel made entirely of real wo		r and appearance. For making a shelf on the wall and/or furniture	e. The solid lumber p	oanel is constructed			
Ec	contial characteristics relevan	nt for assessing its safety (Internal Risk Analysis Part II)					
The following points must be taken into acco risks: - the aspects for assessing safety (page	alysis of the risks potentially asso unt when analysing the possible 1) - all phases of the life cycle	(according to §9 (2) S.2 EU 2023/988 ***) ociated with the product in terms of possible hazards(Sheet 4) Brief description of the ris	iks				
(page 2) - the different consumer categories	Sneet 3)						
	Risk assessmen	t .	Yes	No			
There is a risk of confusion with food due to smell, appearance, shape, packaging, product presentation of the item.				•			
There is a risk of confusion with toys due to smell, appearance, shape, packaging, product presentation of the item.				•			
The product exhibits under normal and forest children, people with reduced abilities, pregn	0	•					
Product or a substance can cause a negative	0	•					
Dangers may arise through an influence of the product.	0	•					
All risks associated with the product are assessed negligible, taking into account the likelihood and extent of damage.				0			
RESULT:	The risk anal	ysis part 1 and part 2 are sufficient. Parts III and IV do not	need to be comple	eted.			
	Person responsible for	this technical documentation and risk analysis					
Surname	Surname Jan-Willem Smits (CFO Deli Home)						
Signature		K-					
		Change history					
Date of the respective revision	amended part	Details of the change					

Letter of Correspondance

We hereby declare that the following articles do not differ in terms of their risk assessment.

The risk assessment can therefore be carried out for the entire group of articles instead of carrying out an individual risk assessment for each article.

List number	Article name or article group name	HORNBACH article numbers	Supplier article numbers	GTINs
1	Timmerpaneel Beuken B/C 18mm 200X40cm	12182814	123135951	4306516990375
2	Timmerpaneel Beuken B/C 18mm 120X60cm	12182828	123135956	4306516990474
3	Timmerpaneel Beuken B/C 18mm 200X60cm	12182826	123135952	4306516990450
4	Timmerpaneel Beuken B/C 18mm 120X30cm	12182816	123135954	4306516990399
5	Timmerpaneel Beuken B/C 18mm 120X40cm	12182818	123135955	4306516990337
6	Timmerpaneel Beuken B/C 18mm 200X30cm	12182819	123135950	4306516990382
7	Timmerpaneel Beuken B/C 18mm 120X20cm	12182830	123135953	4306516990498
8	Timmerpaneel Beuken B/C 18mm 200X20cm	12182820	123135949	4306516990320
9	Timiner parieer beaken by a Tomin 200x20cm	12102020	123133343	4300310330320
10				
11				
12				
13				
14				
15				
16				
17				
18				
19				
20				
21				
22				
23				
24				
25				
26				
27				
28				
29				
30				
31				
32				
33				
34				1
35				
36				
37				
38				
39				
40				
41				
42				
43				
44				
45				
46				
47				
48				
49				